




Batch nr:

**Service • Assistenza • Dienstverlening • Serwis
Servis • Szerviz • Сервисная служба**

Name • Nom • Nome • Naam
Nazwa • Jméno • Názov • Név
Denumire • Isim • Название


Nr. • No. • N° • Номер • Č. • Sz


Typ • Type • Tip • Típus • Tipo
Тип



A		10x40	x31
B		7x60	x3
C		7x50	x6
D		D35	x2
E		M6x60	x4
F		M6x10x13	x4
G		D8x20x10	x1
H		D8xD28x20	x1


J		3,5x40	x6
K		D25x4	x2
N		D15x3	x4
L		D4x13	x6
M		D15x18	x4
P		4mm	x1
Q		GLUE	x1






A		10x40	x31
B		7x60	x3
C		7x50	x6
D		D35	x2
E		M6x60	x4
F		M6x10x13	x4
G		D8x20x10	x1
H		D8xD28x20	x1

J		3,5x40	x6
K		D25x4	x2
N		D15x3	x4
L		D4x13	x6
M		D15x18	x4
P		4mm	x1
Q		GLUE	x1






2




B		7x60	x2
---	---	------	----

3




D		D35	x2
N		D15x3	x4

4




G		7x60	x1
---	---	------	----



5






H		7x50	x2
---	---	------	----


6




E		M6x60	x4
F		M6x10x13	x4


B		7x60	x1
C		7x50	x2
K		D25x4	x2



7




C		7x50	x4
---	---	------	----

8



L		D4x13	x6
M		D15x18	x4

J		3,5x40	x6
---	---	--------	----